

# CHEVRON'S ECUADOR CASE

## WATER SAMPLES FROM CONTAMINATED SITES

Of 329 water samples analyzed by both sides from 34 inspected sites,  
324 (98%) violate Ecuadorian law

Inspected Site	Chevron Samples			Affected Community Samples		
	Water Samples Analyzed by Chevron	Number that Violate Ecuadorian Law*	Percentage that Violate Ecuadorian Law	Water Samples Analyzed by Communities	Number that Violate Ecuadorian Law*	Percentage that Violate Ecuadorian Law
SA-6	14	14	100%	-	-	
SA-21	6	6	100%	-	-	
SA-10	1	1	100%	1	1	100%
SA-65	1	1	100%	2	2	100%
SA-51	2	2	100%	1	1	100%
SA-57	5	5	100%	-	-	-
SA-53	1	1	100%	2	2	100%
SA-94	3	3	100%	2	2	100%
SSF-67	8	8	100%	4	4	100%
SSF-48	1	1	100%	1	1	100%
SA-18	9	8	89%	4	4	100%
SA-85	4	3	75%	3	3	100%
SA-14	8	8	100%	6	6	100%
SA-13	10	10	100%	4	4	100%
SSF-08	4	4	100%	4	4	100%
SSF-04	2	2	100%	1	1	100%
SSF-07	10	10	100%	-	-	-
SSF-21	3	2	67%	1	1	100%
SSF-13	3	3	100%	3	3	100%
SSF-18	6	6	100%	2	2	100%
SSF-24	5	5	100%	3	3	100%
SSF-27	7	7	100%	1	1	100%
SSF-45 <sup>a</sup>	7	7	100%	3	2	66%
SSF-38	9	9	100%	4	4	100%
LAGO-02	9	9	100%	1	1	100%
LAGO-06	20	20	100%	-	-	-
SACHA CENTRAL	16	16	100%	4	4	100%
SSF- NORTE	9	9	100%	-	-	-
LAGO NORTE	6	6	100%	8	8	100%
SSF-SUR	12	12	100%	6	6	100%
SSF-CENTRAL	3	3	100%	2	2	100%
SSF-SW	10	10	100%	3	3	100%
SACHA NORTE 2	19	19	100%	-	-	-
AGUARICO	15	15	100%	5	4	80%
<b>TOTAL</b>	<b>248</b>	<b>245</b>	<b>99%</b>	<b>81</b>	<b>79</b>	<b>97%</b>

\*Decreces 1215 and 3516, which regulate environmental pollution in Ecuador

### CONCLUSIONS:

- (1) OF ALL THE WATER SAMPLES REPORTED TO THE COURT, 324 OF 329 (98%) VIOLATE ECUADORIAN LAW.
- (2) OF EVERY SITE INSPECTED, 100% HAD WATER SAMPLES WITH TOXIC LEVELS THAT VIOLATE ECUADORIAN LAW.

# CHEVRON'S ECUADOR CASE

## COMMUNITY WATER SAMPLES AT CONTAMINATED SITES

Of 81 water samples analyzed by affected communities at 34 inspected sites, 79 (97%) violate Ecuadorian law

Inspected Site	Water Samples Analyzed by Affected Communities	Number that Violate Ecuadorian Law*	Percentage that Violate Ecuadorian Law
SA-6	-	-	-
SA-21	-	-	-
SA-10	1	1	100%
SA-65	2	2	100%
SA-51	1	1	100%
SA-57	-	-	-
SA-53	2	2	100%
SA-94	2	2	100%
SSF-67	4	4	100%
SSF-48	1	1	100%
SA-18	4	4	100%
SA-85	3	3	100%
SA-14	6	6	100%
SA-13	4	4	100%
SSF-08	4	4	100%
SSF-04	1	1	100%
SSF-07	-	-	-
SSF-21	1	1	100%
SSF-13	3	3	100%
SSF-18	2	2	100%
SSF-24	3	3	100%
SSF-27	1	1	100%
SSF-45 <sup>a</sup>	3	2	66%
SSF-38	4	4	100%
LAGO-02	1	1	100%
LAGO-06	-	-	-
SACHA CENTRAL	4	4	100%
LAGO NORTE	8	8	100%
SSF-SUR	6	6	100%
SSF-SW	3	3	100%
SSF-CENTRAL	2	2	100%
SSF-NORTE	-	-	-
SACHA NORTE 2	-	-	-
AGUARICO	5	4	80%
<b>TOTAL</b>	<b>81</b>	<b>79</b>	<b>97%</b>

\*Decrees 1215 and 3516, which regulate environmental pollution in Ecuador

# CHEVRON'S ECUADOR CASE

## CHEVRON WATER SAMPLES FROM CONTAMINATED SITES

Of 248 water samples analyzed by Chevron at 34 inspected sites, 245 (99%) violate Ecuadorian law

Inspected Site	Water Samples Analyzed by Chevron	Number that Violate Ecuadorian Law*	Percentage that Violate Ecuadorian Law
SA-6	14	14	100%
SA-21	6	6	100%
SA-10	1	1	100%
SA-65	1	1	100%
SA-51	2	2	100%
SA-57	5	5	100%
SA-53	1	1	100%
SA-94	3	3	100%
SSF-67	8	8	100%
SSF-48	1	1	100%
SA-18	9	8	89%
SA-85	4	3	75%
SA-14	8	8	100%
SA-13	10	10	100%
SSF-08	6	6	100%
SSF-04	2	2	100%
SSF-07	10	10	100%
SSF-21	3	2	67%
SSF-13	3	3	100%
SSF-18	6	6	100%
SSF-24	5	5	100%
SSF-27	7	7	100%
SSF-45A	7	7	100%
SSF-38	9	9	100%
LAGO-02	9	9	100%
LAGO-06	20	20	100%
SACHA CENTRAL	16	16	100%
LAGO NORTE	4	4	100%
SSF-SUR	12	12	100%
SSF-SW	10	10	100%
SSF-CENTRAL	3	3	100%
SSF-NORTE	9	9	100%
SACHA NORTE 2	19	19	100%
AGUARICO	15	15	100%
<b>TOTAL</b>	<b>248</b>	<b>245</b>	<b>99%</b>

\*Decrees 1215 and 3516, which regulate environmental pollution in Ecuador